



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Shannon			System ID Number:		IL0150300		Current Inventory Date:		4/2/2025			
*Please enter totals in the empty box next to each category	Total Service lines:	390	Total Lead:	2	Total Non-Lead:	365	Total Galvanized Requiring replacement:	7	Total Unknown:	16	Website link to Material Inventory:				

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting "P" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacemnt (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
CHURCH BLDG	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
CHURCH BLDG	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
1 CONVENIENCE BLVD	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
109 COUNTRYSIDE DR	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
118 COUNTRYSIDE DR	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
209 COUNTRYSIDE DR	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
110 E ARCH ST	LC5T009	N	N	Unknown	Unknown	Survey Response	C	C	C, P	NL	N	N/R	N				
116 E ARCH ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
202 E ARCH ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, P	NL	N	N/R	N				
206 E ARCH ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C, P	NL	N	N/R	N				
210 E ARCH ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
217 E ARCH ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, P	NL	N	N/R	N				
2 E BADGER ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
118 E BADGER ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
202 E BADGER ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P	NL	N	N/R	N				
218 E BADGER ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, P	NL	N	N/R	N				
218 E BRADSHAW ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
206 E COUNTRYSIDE	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
218 E COUNTRYSIDE	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
17 E DIVISION	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
11 E DIVISION RD	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
105 E DIVISION RD	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
118 E DIVISION ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
1 E DIVISION ST, Apt 3	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C	NL	N	N/R	N				
202 E ELIZABETH	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Shannon			System ID Number:		IL0150300		Current Inventory Date:		4/2/2025							
*Please enter totals in the empty box next to each category	Total Service lines:		390		Total Lead:	2		Total Non-Lead:	365		Total Galvanized Requiring replacement:	7		Total Unknown:	16		Website link to Material Inventory:		

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
13 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
13.5 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
14 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
22.5 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
30 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
34 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
37 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
102 E MARKET ST	LC2T002	N	N	Unknown	Unknown	Survey Response	L	L	C	L	N	5/13/2024	N				
106 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
113 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, L, C, G	NL	N	N/R	N				
114 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
201 E MARKET ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
202 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
206 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
213 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
217 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
317 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
14.5 E MARKET ST, Apt 1	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
14.5 E MARKET ST, Apt 2	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
217 E ROE	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
102 E SHELLY ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
117 E SHELLY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
202 E SHELLY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
218 E SHELLY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
106 E SHELLY ST, Apt 8	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
206 HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
135 HICKORY ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
97 HIGHCREST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
1 HIGHCREST COURT	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
101 HIGHCREST CT	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C	NL	N	N/R	N				
105 HIGHCREST CT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
109 HIGHCREST CT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
113 HIGHCREST CT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
117 HIGHCREST CT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
201 HIGHCREST CT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	G	NL	N	N/R	N				
205 HIGHCREST CT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
209 HIGHCREST CT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
93 HIGHCREST CT	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
717 KENNEDY ST	LC5T010	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
718 KENNEDY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
717 MACARTHUR ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name	Village of Shannon			System ID Number:	IL0150300	Current Inventory Date:	4/2/2025				
*Please enter totals in the empty box next to each category	Total Service lines:	390	Total Lead:	2	Total Non-Lead:	365	Total Galvanized Requiring replacement:	7	Total Unknown:	16	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
410 MARKET	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
10 N BRD	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	U	U	N	5/13/2024	N				
1 N BRD ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
6 N BRD ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
15 N BRD ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
18 N BRD ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
101 N BRD ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
18 N CEDAR ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P	NL	N	N/R	N				
13 N HICKORY ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P	NL	N	N/R	N				
17 N HICKORY ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
13 N LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
17 N LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
101 N LINN ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P	NL	N	N/R	N				
105 N LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
109 N LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
113 N LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
117 N LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
10 N LOCUST OFFICE	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
2 N LOCUST ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
2.5 N LOCUST ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
109 N RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
110 N RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
117 N RIDGE ST	LCST018	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C	NL	N	N/R	N				
10 N SHANNON RD	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
13 N SHANNON RD	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C, G	NL	N	N/R	N				
113 N SHANNON RTE	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
114 N SHANNON RTE	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
101 N STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
118 N STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
210 N STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
15 N STANTON ST (LIMITED PARTNERSHIP)	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
317 PINE LANE	N/A	N	N	Unknown	Unknown	Visual Inspection	P	P	C	NL	N	N/R	N				
26 N STANTON ST (MANOR APTS)	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
BRYAN'S REPAIR SERV (17 N Stanton)	N/A	N	N	Unknown	Unknown	Survey Response	G	C	C	GRR	N	5/13/2024	N				
13 S CEDAR ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
502 S CEDAR ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
504 S CEDAR ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
506 S CEDAR ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
508 S CEDAR ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
510 S CEDAR ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
512 S Cedar St	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Shannon			System ID Number:		IL0150300		Current Inventory Date:		4/2/2025				
*Please enter totals in the empty box next to each category	Total Service lines:	390	Total Lead:	2	Total Non-Lead:	365	Total Galvanized Requiring replacement:	7	Total Unknown:	16	Website link to Material Inventory:					

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
514 S CEDAR ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
516 S CEDAR ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
406 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
413 S CHESTNUT ST	LCST021	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
202 S CHESTNUT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
9 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
13 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
17 S CHESTNUT ST	LC3T004	N	N	Unknown	Unknown	Visual Inspection	G	G	C, G	GRR	N	5/13/2024	N				
18 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
105 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	G	NL	N	N/R	N				
109 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, G	NL	N	N/R	N				
110 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
113 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
114 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C, G	NL	N	N/R	N				
117 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
118 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
201 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	G	NL	N	N/R	N				
205 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
206 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
209 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
210 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
214 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
218 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
302 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
306 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
310 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Visual Inspection	G	G	P, C, G	GRR	N	5/13/2024	N				
314 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	U	U	U	U	N	5/13/2024	N				
318 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	U	U	N	5/13/2024	N				
401 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	G	NL	N	N/R	N				
402 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
409 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
410 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C	NL	N	N/R	N				
414 S CHESTNUT ST	LCST011	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
417 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
418 S CHESTNUT ST	LC3T005	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C	NL	N	5/13/2024	N				
502 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
510 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C, G	NL	N	N/R	N				
514 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
518 S CHESTNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
102 S CHESTNUT ST, Apt 2	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
217 S CHESTNUT ST, Apt 3	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Shannon			System ID Number:		IL0150300		Current Inventory Date:		4/2/2025				
*Please enter totals in the empty box next to each category	Total Service lines:	390	Total Lead:	2	Total Non-Lead:	365	Total Galvanized Requiring replacement:	7	Total Unknown:	16	Website link to Material Inventory:					

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
9 S HICKORY ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C	NL	N	N/R	N				
17 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
101 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
102 S HICKORY ST	LCST012	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
109 S HICKORY ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C, G	NL	N	N/R	N				
113 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
117 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
118 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
202 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
214 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P	NL	N	N/R	N				
301 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
305 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	G	NL	N	N/R	N				
309 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
317 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
401 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
402 S HICKORY ST	LCST013	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
405 S HICKORY ST	LCST014	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
409 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
410 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
413 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
417 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
418 S HICKORY ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
509 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
517 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
601 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
605 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
609 S HICKORY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
110 S HICKORY ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
700 S KENNEDY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	G	NL	N	N/R	N				
701 S KENNEDY ST	N/A	N	N	Unknown	Unknown	Survey Response	C	CC	P, C	NL	N	N/R	N				
1 S LINN ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
102 S LINN ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
105 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
106 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
109 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
110 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
113 S LINN ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
114 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
117 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
118 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
202 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Shannon			System ID Number:		IL0150300		Current Inventory Date:		4/2/2025				
*Please enter totals in the empty box next to each category	Total Service lines:	390	Total Lead:	2	Total Non-Lead:	365	Total Galvanized Requiring replacement:	7	Total Unknown:	16	Website link to Material Inventory:					

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
205 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
206 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, G	NL	N	N/R	N				
209 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
210 S LINN ST	LCST015	N	N	Unknown	Unknown	Survey Response	C	C	G	NL	N	N/R	N				
213 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
217 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	G	NL	N	N/R	N				
218 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
301 S LINN ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
302 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
306 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
309 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
314 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
317 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
401 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
402 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
406 S LINN ST	LCST008	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
409 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
410 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
413 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
417 S LINN ST	LCST017	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
418 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
501 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
502 S LINN ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	5/13/2024	N				
505 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
509 S LINN ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C, G	NL	N	N/R	N				
514 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
517 S LINN ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C	NL	N	N/R	N				
601 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
602 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	G	NL	N	N/R	N				
606 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
610 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
611 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
617 S LINN ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
618 S LINN ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
518.5 S LINN, Apt 1	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, G	NL	N	N/R	N				
18 S LOCUST ST ELE	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
701 S MAC ARTHUR ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
718 S MACARTHUR ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
101 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
102 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
108 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Shannon			System ID Number:		IL0150300		Current Inventory Date:		4/2/2025				
*Please enter totals in the empty box next to each category	Total Service lines:	390	Total Lead:	2	Total Non-Lead:	365	Total Galvanized Requiring replacement:	7	Total Unknown:	16	Website link to Material Inventory:					

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
109 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
118 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
201 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
202 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
209 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
210 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
213 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
217 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	G	NL	N	N/R	N				
218 S RIDGE ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
301 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
302 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
306 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
309 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
310 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	UNL	NL	N	N/R	N				
314 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
317 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
318 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
401 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
402 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
409 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
417 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, L, C, G	NL	N	N/R	N				
501 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
502 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
509 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
510 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
517 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
518 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
601 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
602 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
605 S RIDGE ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
606 S RIDGE ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P	NL	N	N/R	N				
609 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
610 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
617 S RIDGE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
801 S SHANNON RD	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
13 S SHANNON RTE	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
1 S STANTON	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C	NL	N	N/R	N				
101 S STANTON	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
109 S STANTON	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
206 S STANTON	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P	NL	N	N/R	N				
13 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C, G	NL	N	N/R	N				



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Shannon			System ID Number:		IL0150300		Current Inventory Date:		4/2/2025				
*Please enter totals in the empty box next to each category	Total Service lines:	390	Total Lead:	2	Total Non-Lead:	365	Total Galvanized Requiring replacement:	7	Total Unknown:	16	Website link to Material Inventory:					

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
17 S STANTON ST	LC5T019	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C, G	NL	N	N/R	N				
18 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
110 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
201 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
202 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
209 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
213 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
214 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
217 S STANTON ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
301 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
302 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
305 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
309 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
310 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
317 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
318 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
410 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
502 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
514 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
518 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
602 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
614 S STANTON ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
106 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
114 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
201 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
202 S Walnut St	LC3T003	N	N	Unknown	Unknown	Visual Inspection	G	G	C, G	GRR	N	5/13/2024	N				
209 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P	NL	N	N/R	N				
210 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
217 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
301 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
302 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P	NL	N	N/R	N				
309 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
317 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
402 S WALNUT ST	LC5T007	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
409 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
410 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
501 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
505 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
510 S WALNUT ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P	NL	N	N/R	N				
513 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
602 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Shannon			System ID Number:		IL0150300		Current Inventory Date:		4/2/2025				
*Please enter totals in the empty box next to each category	Total Service lines:	390	Total Lead:	2	Total Non-Lead:	365	Total Galvanized Requiring replacement:	7	Total Unknown:	16	Website link to Material Inventory:					

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
610 S WALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
605 SHANNON RTE	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
15635 SHANNON RTE	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P	NL	N	N/R	N				
15731 SHANNON RTE	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
16370 SHANNON RTE	N/A	N	N	Unknown	Unknown	Visual Inspection	P	P	P	NL	N	5/13/2024	N				
518 SOUTH WALNUT ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
112 SRIDGE ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	5/13/2024	N				
114 W MARKET ST (SEAMLESS GUTTERS)	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
FIRE STATION	N/A	N	N	Unknown	Unknown	Survey Response	P, C	P, C	P, C	NL	N	N/R	N				
2 E MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
301 SUNRISE DR	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
302 SUNRISE DR	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
306 SUNRISE DR	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
309 SUNRISE DR	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
310 SUNRISE DR	LC5T020	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
314 SUNRISE DR	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
317 SUNRISE DR	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
318 SUNRISE DR	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
401 SUNSET COURT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
402 SUNSET COURT	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
410 SUNSET COURT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
318 SUNSET CT	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
506 SWALNUT ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
117 W ARCH ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, L	NL	N	N/R	N				
302 W ARCH ST	N/A	N	Y	Unknown	Unknown	Survey Response	C	C	C, P	NL	N	N/R	N				
401 W ARCH ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
402 W ARCH ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P	NL	N	N/R	N				
317 W ARCH ST LQD	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
18 W BADGER ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
18.5 W BADGER ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
22 W BADGER ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
112 W BADGER ST	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	P, C, G	NL	N	N/R	N				
217 W BADGER ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
418 W BADGER ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
2 W BRADSHAW ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
14 W BRADSHAW ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
117 W COOK ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
13 W COOK-17W ELIZ	N/A	Y	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
9 W DIVISION RD	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
201 W DIVISION RD	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
202 W DIVISION RD	N/A	Y	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Shannon			System ID Number:		IL0150300		Current Inventory Date:		4/2/2025				
*Please enter totals in the empty box next to each category	Total Service lines:	390	Total Lead:	2	Total Non-Lead:	365	Total Galvanized Requiring replacement:	7	Total Unknown:	16	Website link to Material Inventory:					

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
205 W DIVISION RD	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
210 W DIVISION RD	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
217 W DIVISION RD	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
218 W DIVISION RD	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
117 W DIVISION ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
213 W DIVISION ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
118 W ELIZABETH ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P	NL	N	N/R	N				
2 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C, G	NL	N	N/R	N				
6 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
6.5 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
10 W MARKET ST	N/A	N	N	Unknown	Unknown	Visual Inspection	G	G	P, C, G	GRR	N	5/13/2024	N				
10.5 W MARKET ST	N/A	N	N	Unknown	Unknown	Visual Inspection	G	G	P, C, G	GRR	N	5/13/2024	N				
13 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
22 W Market St	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P	NL	N	N/R	N				
106 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P	NL	N	N/R	N				
110 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
201 W MARKET ST	LC1T001	N	N	Unknown	Unknown	Visual Inspection	L	L	UNL	L	N	5/13/2024	N				
202 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
217 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
218 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C, G	NL	N	N/R	N				
302 W MARKET ST	N/A	N	N	Unknown	Unknown		U	U	U	U	N	5/13/2024	N				
310 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
317 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C, G	NL	N	N/R	N				
401 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
402 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
409 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
413 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C, G	NL	N	N/R	N				
414 W MARKET ST	LC3T006	N	N	Unknown	Unknown	Survey Response	G	G	P, C, G	GRR	N	5/13/2024	N				
501 W MARKET ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
2.5 W MARKET ST, Apt 1	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C, G	NL	N	N/R	N				
9 W ROE ST	N/A	N	N	Unknown	Unknown	Survey Response	C	C	G	NL	N	N/R	N				
117 W SOUTH ST	N/A	N	N	Unknown	Unknown	Survey Response	P	P	C	NL	N	N/R	N				
409 W SUNSET COURT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	P, C	NL	N	N/R	N				
309 W SUNSET CT	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
317 W SUNSET CT	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
214 N STANTON ST (TRUCK WASH)	N/A	N	N	Unknown	Unknown	Survey Response	P	P	P, C	NL	N	N/R	N				
PARSONAGE	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
St Wendelins Rectory	N/A	N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				